
Chestnut Street over South Douglas Creek Bridge Replacement


PPRTA - Board
September 9, 2015
Mike Chaves, PE - Engineering Manager
Aaron Egbert, PE - Senior Civil Engineer




Location Map



Sketch



July 2014 Culvert Failure




July 2014 Culvert Repair




August 10, 2015 Storm Event





August 10, 2015 Storm Event





August 2015 Culvert Failure



Exposed Utilities



Culvert Outlet





Collapsed Culvert





















Next steps

- Accelerated the Replacement Project
- \$500,000 approved by PPRTA
- Schanel Construction is currently working on Phase 1 of the construction and stabilization
- HDR Engineering is working on Preliminary Design
- Multiple options
- Bridge structure type will affect schedule

	U/S BERM	6195		
Print Dates 8/24/2015 Phint Dates 8/24/2015 Phint Name: Castnut.DES_PLANOL.dgn Horiz. Souls: 1340 Unit Informedion Unit Leader Lrifols	N CHESTWUL ST		CHESTNUT PLAN SHEET Dealgrars XXXXXXXX Structurs X-30X-XX Dealgrars XXXXXXXXX Structurs X-30X-XX Sharel Swint Skylon XXXXXXX XXXXXX XXXXXX XXXXXX XXXXXX XXXX	Project No./Code Project Number Coda Sheet Number XXX

